Oil Field Environmental Incident Summary

Incident: 20160608171514 **Date/Time of Notice:** 06/08/2016 17:15 Responsible Party: ENERPLUS RESOURCES USA CORPORATION **ENERPLUS RESOURCES USA CORPORATION**

Well Name: BARN 147-94-13A-24H Field Name: MCGREGORY BUTTES

Well File #: 30866

Date Incident: 6/8/2016 Time Incident: 13:00 Facility ID Number: DUNN **Rna**: 94 County: **Twp:** 147 Sec: 13 Qtr:

Location Description: Prairie

Submitted By: Tony Lucero Received By:

Contact Person: Chuck Antle

US BANK TOWER 950 17TH ST STE 2200 DENVER, CO 80202

General Land Use: Pasture Affected Medium: Topsoil

2 Mile Distance Nearest Occupied Building: 2 Mile Distance Nearest Water Well:

Type of Incident: Fire

Release Contained in Dike: Yes - On Facility Site Reported to NRC: No

Spilled Units Recovered Units Followup **Units**

Oil **Brine**

Other

Description of Other Released Contaminant:

Grass fire on pasture land adjacent to the well pad. All affected area was within the lease boundary.

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

No applicable health or safety hazards.

Areal Extent:

An estimated 1,650 sq. ft. of pasture land adjacent to our well pad was affected.

Potential Environmental Impacts:

An estimated 1,650 sq. ft. of pasture land adjacent to our well pad was affected. All affected area was within the lease boundary.

Action Taken or Planned:

Follow applicable inspection and maintenance procedures.

Wastes Disposal Location: NA

Agencies Involved: BLM, BIA, Three Affiliated Tribes (MHA)

Updates

Date: 6/9/2016 Status: Reviewed - Assigned to Other Agency Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report the fire was contained to lease land. Location is within MHA nation. Report forwarded to MHA environmental, BIA, and EPA.